


PRECISION PRESSURE CALIBRATOR 700 BAR/10000PSI

TYPE: PRECISION PRESSURE CALIBRATOR



PRECISION PRESSURE CALIBRATOR 700 BAR/10000PSI

TYPE: PRECISION PRESSURE CALIBRATOR

FUNCTIONAL SPECIFICATIONS

Accuracy	+0.05% of full scale.
Range	700 BAR, 10000PSI
Overload Maximum	+50%F.S.
Overload Alarm	Activates at +20% Full Scale
Resolution	Minimum 5 digits
Display	2 Line, 16-character LCD
Display Update	Twice per second
mA Input	4-20mA or 10-50mA
Voltage Input	0-30V
Pressure Switch	Supply maximum 9Vdc

PRECISION PRESSURE CALIBRATOR 700 BAR/10000PSI

TYPE: PRECISION PRESSURE CALIBRATOR

PHYSICAL SPECIFICATIONS

Temperature Compensation	0°C to 50°C
Battery	9Vdc Alkaline
Approximately 15-hours battery life	Low Battery Indicator at 7 volts
Weight	400g
Dimensions (L x W x H)	160 × 90 × 45 mm

APPLICATIONS: USED FOR PRESSURE CALIBRATION.

CODE: DSEPPC00700BAR0021

MANUAL NO.: 21